



Nick Mob: 0432 199 016
Head Office Fax: 07 49514117
Email: nick@ausnorthasbestos.com.au
diane@ausnorthasbestos.com.au
Head Office: PO Box 3500, North Mackay 4740

WORK CLEARANCE CERTIFICATE

Job Number	A00790
Date	16.7.2018
Area of Removal	Removal of 2 asbestos core fire doors from Building 361.
Client Name	CQ University North Rockhampton
Postal Address	Building 37, Level 1, Bruce Highway, North Rockhampton 4702
Site Address	Building 361, CQU Campus, North Rockhampton.
Name of Supervisor/Licence Details.	Brendan Housman
Licence Details	<i>Class A Asbestos Removal: 2308445</i>

The area of removal has been visually inspected by a competent person independent of the removal. It has been visually assessed to ensure proper decontamination procedures have been used and that no evidence of asbestos containing material remains in the affected area.

The area is now deemed safe to reoccupy.

Name of inspector	Nick Trimble		
Signature			
Date of inspection	16.7.2018	Time of inspection	1.00pm

Assessor Checklist

To be used by the competent assessor in instances where a NATA approved hygienist is not monitoring the works.

	Yes	No
Do you have a copy of the asbestos removal control plan/SWMS?	✓	
Do you have a copy of the notification form?	✓	
Is the removal work consistent with the control plan?	✓	
Visual Inspection		
Inspection of the specific removal area found no visual asbestos as a result of the removal work carried out. (Timbers have been de-nailed, no visual dust or debris.)	✓	
Is the area safe to reoccupy?	✓	
If no then the removal team must be instructed to complete the decontamination to an acceptable finish.		
2nd Visual Inspection		
Inspection of the specific removal area found no visual asbestos as a result of the removal work carried out. (Timbers have been de-nailed, no visual dust or debris.)		
Is the area safe to reoccupy?		

Name of Inspector:			
Signature:			
Date of inspection		Time of Inspection	